




ALBIZIA COTES REPARATION CHASSIS

24

03/07/03



Tolérances Générales

Angles : + ou - $0^\circ 30'$ Cotes : + ou - 2 mm

Carrossage AV 0 + ou - 2°

AR 0 + ou - 2°

Parallelisme : 0 - 2mm

